



Technical Specifications	
Accuracy	±0.03mm/±0.0005"
Resolution	0.01mm/0.0005"
Working Range	150mm/6"
Power Supply	1×LR44 Batter
Working temperature	32°F to 122°F (0°C to 50°C)
Working Humidity	≤85%

Button Function	
OFF ON	turns the power completely on or off
ZERO	short pressing sets display to at zero any position
mm inch/F	switch between mm , inch and F by short pressing, mm display in Metric mode inch display in Inch mode F display in Fraction mode



Measurements



Battery Installation



Trouble Shooting

Problem	Possible Cause	Solution
No display	Lower voltage	Replace Battery
No display	Bad Contact	Clean Battery
Flashing Digits	Lower voltage	Replace battery
Erratic or Frozen Display	Internal error	Remove battery wait 1 minute and replace

⚠ Notices:

1. Reading the instruction sheet carefully before using the tool
2. This is a sensitive precision tool. Do not disassemble it by yourselves or drop it